

<b>Project No.</b>	<b>Client</b>	<b>Location</b>	<b>Boring No.</b>	<b>Monitoring Well No.</b>	<b>Date</b>
00445	Beacon Bay Auto Wash	481 E. 17 <sup>th</sup> St., Costa Mesa	CB3		August 3, 2005
<b>PID</b>	<b>BLOWS/ft. Sampler</b>	<b>DEPTH in feet</b>	<b>USCS Designation &amp; Soil Type</b>	<b>Color</b>	<b>Secondary Characteristics</b>
0	6-12-50/4"	<b>5</b>	Silty Clay (CL)	Dark Brown	Stiff, SI Moist, No Odor
0	6-10-13	<b>10</b>			
0	9-12-18	<b>15</b>			
40	10-13-19	<b>20</b>	Silty Sands (SM)	Light Tan to Medium Brown	M. Dense, Wet, SI Odor
0	8-10-17	<b>25</b>			No Odor
50	8-16-24	<b>30</b>	Clayey Sands (SC)	Dark Grey	M. Dense, Wet, SI Odor
0	7-11-16	<b>35</b>	Silty Clay (CL)	Brownish Grey	Stiff, Wet, No Odor
<b>Field Engineer</b>	<b>Drilling Contractor</b>	<b>Drilling Foreman</b>	Boring terminated at 35'. Groundwater encountered at 16-17'. Boring backfilled with soil from boring. Overflow soil drummed and manifested.		
M. Anselmo	J & H - Hollow Stem	Conrad			